

Flood Control Project Maintenance**2013 Structure Summary Report****Overall Unit and Item Ratings****Butte County Public Works Department****Big Chico Creek Diversion Structure**

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A
	Culverts: Inlets / Outlets	A
	Culverts: Breaks / Holes / Cracks	A
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	A
	Electric Gate Operators	N
	Manual Gate Operators	A
	Concrete Surfaces	A
	Concrete Tilting / Settlement	A
	Concrete Foundations	A
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	A
	Safety	A
	Operation & Maintenance Manual	A

Flood Control Project Maintenance**2013 Structure Summary Report****Overall Unit and Item Ratings****Butte County Public Works Department (cont.)****Lindo Channel Control Structure**

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A
	Culverts: Inlets / Outlets	A
	Culverts: Breaks / Holes / Cracks	A
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	A
	Electric Gate Operators	N
	Manual Gate Operators	A
	Concrete Surfaces	A
	Concrete Tilting / Settlement	A
	Concrete Foundations	A
	Security Fencing	N
	Closure Structures	A
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	A
	Safety	A
	Operation & Maintenance Manual	A

Flood Control Project Maintenance**2013 Structure Summary Report****Overall Unit and Item Ratings****Butte County Public Works Department (cont.)****Lindo Channel Diversion Weir**

Overall Unit Rating	Rated Item	Item Rating
A	Photo Documentation	N
	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A
	Culverts: Inlets / Outlets	N
	Culverts: Breaks / Holes / Cracks	N
	Metal Pipes	N
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	N
	Electric Gate Operators	N
	Manual Gate Operators	N
	Concrete Surfaces	A
	Concrete Tilting / Settlement	A
	Concrete Foundations	A
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	N
	Monolith Joints	A
	Safety	A
	Operation & Maintenance Manual	A

Flood Control Project Maintenance**Unit Cover Sheet****2013 Structure Inspection Results****Butte County Public Works Department**

Structure
Big Chico Creek Diversion Structure

Structure Rating	A
Date of Inspection	07/30/2013
DWR Inspector	Matthew Hoffman
Accompanied By	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2013

Butte County Public Works Department

Structure						Structure Length	Inspection Start/End	Inspector
Big Chico Creek Diversion Structure							07/30/2013 07/30/2013	Matthew Hoffman

LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.00	0.00	Structures	Photo Documentation		N		39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	1 Y
2	0.00	0.00	Structures	Vegetation & Obstructions		A	Inspector Comments: Minimal vegetation, the flow does not appear to be impeded.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	2
3	0.00	0.00	Structures	Shoaling / Sedimentation		A	Inspector Comments: There is some sedimentation, it does not appear to impede the flow.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	3
4	0.00	0.00	Structures	Erosion / Bank Caving		A	Inspector Comments: No erosion observed.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	4
5	0.00	0.00	Structures	Revetments		A	Inspector Comments: Riprap is visible and appears to be properly maintained.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	5
6	0.00	0.00	Structures	Encroachments		A	Inspector Comments: No encroachment present.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	6
7	0.00	0.00	Structures	Culverts: Inlets / Outlets		A	Inspector Comments: Minimal sedimentation, the flow does not appear to be impeded.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	7
8	0.00	0.00	Structures	Culverts: Breaks / Holes / Cracks		A	Inspector Comments: The culverts appear to be in good condition.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	8
9	0.00	0.00	Structures	Metal Pipes		N	Inspector Comments: This item does not apply to this inspection.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	9
10	0.00	0.00	Structures	Trash Racks		N	Inspector Comments: This item does not apply to this inspection.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	10
11	0.00	0.00	Structures	Flap Gates		N	Inspector Comments: This item does not apply to this inspection.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	11
12	0.00	0.00	Structures	Sluice/Slide Gates		A	Inspector Comments: Gate appears in good condition.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	12
13	0.00	0.00	Structures	Electric Gate Operators		N	Inspector Comments: This item does not apply to this inspection.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	13
14	0.00	0.00	Structures	Manual Gate Operators		A	Inspector Comments: Manual gate operators appear to be in good condition.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	14
15	0.00	0.00	Structures	Concrete Surfaces		A	Inspector Comments: The concrete surface appears to be in good condition.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	15

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2013

Butte County Public Works Department

Structure						Structure Length	Inspection Start/End	Inspector
Big Chico Creek Diversion Structure							07/30/2013 07/30/2013	Matthew Hoffman

LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
16	0.00	0.00	Structures	Concrete Tilting / Settlement		A	Inspector Comments: No tilting, sliding or settlement observed.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	16
17	0.00	0.00	Structures	Concrete Foundations		A	Inspector Comments: The concrete foundations appear in good condition.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	17
18	0.00	0.00	Structures	Security Fencing		N	Inspector Comments: This item does not apply to this inspection.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	18
19	0.00	0.00	Structures	Closure Structures		N	Inspector Comments: This item does not apply to this inspection.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	19
20	0.00	0.00	Structures	Trash Rakes		N	Inspector Comments: This item does not apply to this inspection.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	20
21	0.00	0.00	Structures	Other Metallic Items		N	Inspector Comments: This item does not apply to this inspection.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	21
22	0.00	0.00	Structures	Monolith Joints		A	Inspector Comments: Monolith joints appear to be in good condition.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	22
23	0.00	0.00	Structures	Safety		A	Inspector Comments: There are hand rails installed.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	23
24	0.00	0.00	Structures	Operation & Maintenance Manual		A	Inspector Comments: Butte County Public Works has a copy of the O&M manual on file. There is not a spot on site to house the O&M manual.	39.763308 ° -121.791903 °	39.763308 ° -121.791903 °	24

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2013

Butte County Public Works Department

Structure	Structure Length	Inspection Start/End	Inspector
Big Chico Creek Diversion Structure		07/30/2013 07/30/2013	Matthew Hoffman

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Photo Documentation

This is a view of the structure from the bike path.

mhoffman_t_20130807_035.JPG



Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Photo Documentation

This is a view of the structure from upstream.

mhoffman_t_20130807_036.JPG



Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Photo Documentation

This is a view of the structure from downstream.

mhoffman_t_20130807_037.JPG



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected, see Inspector Comment

C : Corrected

Flood Control Project Maintenance**Unit Cover Sheet****2013 Structure Inspection Results****Butte County Public Works Department**

Structure
Lindo Channel Control Structure

Structure Rating	A
Date of Inspection	07/30/2013
DWR Inspector	Matthew Hoffman
Accompanied By	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2013

Butte County Public Works Department

Structure						Structure Length	Inspection Start/End	Inspector
Lindo Channel Control Structure							07/30/2013 07/30/2013	Matthew Hoffman

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.00	0.00	Structures	Photo Documentation		N		39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	1 Y
2	0.00	0.00	Structures	Vegetation & Obstructions		M	Inspector Comments: Minimal vegetation, and some trees that may impede the flow close to the gates.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	2
3	0.00	0.00	Structures	Shoaling / Sedimentation		A	Inspector Comments: Minimal shoaling observed.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	3
4	0.00	0.00	Structures	Erosion / Bank Caving		A	Inspector Comments: No erosion observed.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	4
5	0.00	0.00	Structures	Revetments		A	Inspector Comments: Riprap is visible and appears to be properly maintained.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	5
6	0.00	0.00	Structures	Encroachments		A	Inspector Comments: No encroachments observed.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	6
7	0.00	0.00	Structures	Culverts: Inlets / Outlets		A	Inspector Comments: The culverts appear to be in good condition, the flow does not appear to be impeded.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	7
8	0.00	0.00	Structures	Culverts: Breaks / Holes / Cracks		A	Inspector Comments: The culverts appear in good condition.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	8
9	0.00	0.00	Structures	Metal Pipes		N	Inspector Comments: This item does not apply to this inspection.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	9
10	0.00	0.00	Structures	Trash Racks		N	Inspector Comments: This item does not apply to this inspection.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	10
11	0.00	0.00	Structures	Flap Gates		N	Inspector Comments: This item does not apply to this inspection.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	11
12	0.00	0.00	Structures	Sluice/Slide Gates		A	Inspector Comments: Gates appear in good condition.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	12
13	0.00	0.00	Structures	Electric Gate Operators		N	Inspector Comments: This item does not apply to this inspection.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	13
14	0.00	0.00	Structures	Manual Gate Operators		A	Inspector Comments: Manual gate operators appear to be in good condition.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	14
15	0.00	0.00	Structures	Concrete Surfaces		A	Inspector Comments: The concrete surface appears to be in good condition.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	15

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2013

Butte County Public Works Department

Structure	Structure Length	Inspection Start/End	Inspector
Lindo Channel Control Structure		07/30/2013 07/30/2013	Matthew Hoffman

LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
16	0.00	0.00	Structures	Concrete Tilting / Settlement		A	Inspector Comments: No significant areas of tilting, sliding or settlement observed.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	16
17	0.00	0.00	Structures	Concrete Foundations		A	Inspector Comments: The concrete foundation appears to be in good condition.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	17
18	0.00	0.00	Structures	Security Fencing		N	Inspector Comments: This item does not apply to this inspection.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	18
19	0.00	0.00	Structures	Closure Structures		A	Inspector Comments: The closure structure appears in good condition.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	19
20	0.00	0.00	Structures	Trash Rakes		N	Inspector Comments: This item does not apply to this inspection.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	20
21	0.00	0.00	Structures	Other Metallic Items		N	Inspector Comments: This item does not apply to this inspection.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	21
22	0.00	0.00	Structures	Monolith Joints		A	Inspector Comments: Monolith joints appear to be in good condition.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	22
23	0.00	0.00	Structures	Safety		A	Inspector Comments: Hand rails are installed.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	23
24	0.00	0.00	Structures	Operation & Maintenance Manual		A	Inspector Comments: Butte County Public Works has a copy of the O&M manual on file. There is not a spot on site to house the O&M manual.	39.761520 ° -121.797265 °	39.761520 ° -121.797265 °	24

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2013

Butte County Public Works Department

Structure	Structure Length	Inspection Start/End	Inspector
Lindo Channel Control Structure		07/30/2013 07/30/2013	Matthew Hoffman

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Photo Documentation

This is a view of the structure from the bike trail.

mhoffman_t_20130807_039.JPG



Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Photo Documentation

This is a view of the structure from upstream.

mhoffman_t_20130807_040.JPG



Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Photo Documentation

This is a view of the structure from downstream.

mhoffman_t_20130807_041.JPG



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected, see Inspector Comment

C : Corrected

Flood Control Project Maintenance**Unit Cover Sheet****2013 Structure Inspection Results****Butte County Public Works Department**

Structure
Lindo Channel Diversion Weir

Structure Rating	A
Date of Inspection	07/30/2013
DWR Inspector	Matthew Hoffman
Accompanied By	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2013

Butte County Public Works Department

Structure	Structure Length	Inspection Start/End	Inspector
Lindo Channel Diversion Weir		07/30/2013 07/30/2013	Matthew Hoffman

LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
1	0.00	0.00	Structures	Photo Documentation		N		39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	1 Y
2	0.00	0.00	Structures	Vegetation & Obstructions		A	Inspector Comments: There is vegetation, the flow does not appear to be impeded.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	2
3	0.00	0.00	Structures	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sedimentation observed.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	3
4	0.00	0.00	Structures	Erosion / Bank Caving		A	Inspector Comments: No erosion observed.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	4
5	0.00	0.00	Structures	Revetments		A	Inspector Comments: Riprap is visible and appears to be properly maintained.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	5
6	0.00	0.00	Structures	Encroachments		A	Inspector Comments: No encroachments observed.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	6
7	0.00	0.00	Structures	Culverts: Inlets / Outlets		N	Inspector Comments: This item does not apply to this inspection.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	7
8	0.00	0.00	Structures	Culverts: Breaks / Holes / Cracks		N	Inspector Comments: This item does not apply to this inspection.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	8
9	0.00	0.00	Structures	Metal Pipes		N	Inspector Comments: This item does not apply to this inspection.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	9
10	0.00	0.00	Structures	Trash Racks		N	Inspector Comments: This item does not apply to this inspection.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	10
11	0.00	0.00	Structures	Flap Gates		N	Inspector Comments: This item does not apply to this inspection.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	11
12	0.00	0.00	Structures	Sluice/Slide Gates		N	Inspector Comments: This item does not apply to this inspection.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	12
13	0.00	0.00	Structures	Electric Gate Operators		N	Inspector Comments: This item does not apply to this inspection.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	13
14	0.00	0.00	Structures	Manual Gate Operators		N	Inspector Comments: This item does not apply to this inspection.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	14
15	0.00	0.00	Structures	Concrete Surfaces		A	Inspector Comments: Concrete surface appears to be in good condition.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	15

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected, see Inspector Comment
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2013

Butte County Public Works Department

Structure	Structure Length	Inspection Start/End	Inspector
Lindo Channel Diversion Weir		07/30/2013 07/30/2013	Matthew Hoffman

LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
16	0.00	0.00	Structures	Concrete Tilting / Settlement		A	Inspector Comments: There are no significant areas of tilting, sliding or settlement observed.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	16
17	0.00	0.00	Structures	Concrete Foundations		A	Inspector Comments: The concrete foundation appears in to be good condition.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	17
18	0.00	0.00	Structures	Security Fencing		N	Inspector Comments: This item does not apply to this inspection.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	18
19	0.00	0.00	Structures	Closure Structures		N	Inspector Comments: This item does not apply to this inspection.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	19
20	0.00	0.00	Structures	Trash Rakes		N	Inspector Comments: This item does not apply to this inspection.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	20
21	0.00	0.00	Structures	Other Metallic Items		N	Inspector Comments: This item does not apply to this inspection.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	21
22	0.00	0.00	Structures	Monolith Joints		A	Inspector Comments: Monolith joints appear to be in good condition.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	22
23	0.00	0.00	Structures	Safety		A	Inspector Comments: Hand rails are installed.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	23
24	0.00	0.00	Structures	Operation & Maintenance Manual		A	Inspector Comments: Butte County Public Works has a copy of the O&M manual on file. There is not a spot on site to house the O&M manual.	39.762012 ° -121.797330 °	39.762012 ° -121.797330 °	24

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected, see Inspector Comment
C : Corrected

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Structure 2013

Butte County Public Works Department

Structure	Structure Length	Inspection Start/End	Inspector
Lindo Channel Diversion Weir		07/30/2013 07/30/2013	Matthew Hoffman

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Photo Documentation

This is a view of the weir.

mhoffman_t_20130807_038.JPG



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing
CO : Completely Obstructing
N : Not Inspected, see Inspector Comment

C : Corrected